

**TECHNICAL DATA** 

# Fluke OC4USB USB Interface Cable



## **Key features**

- Supports the Fluke 120 Series and Fluke 190 Series ScopeMeter test tools, as well as the 43, 43B and 430 Series <u>Power Quality analyzers</u>
- Supports Windows Vista/XP/2000/Me/98 SE
- Cable length 1.5 m (4.9 ft)

(see instrument specifications)

## **Product overview: Fluke OC4USB USB Interface Cable**

Safety-designed interface cable to connect the optically-isolated serial interface port of ScopeMeter or Power Quality Analyzer to a standard USB-interface on your PC. Optical isolation allows you to float your instrument at mains voltages or beyond, while being connected to your PC.



# **Ordering information**





### $\textbf{Fluke}. \ \textit{Keeping your world up and running.} \\ \textbf{@}$

### Fluke Corporation

PO Box 9090, Everett, WA 98206 U.S.A.

### For more information call:

In the U.S.A. (800) 443-5853 In Europe/M-East/Africa +31 (0)40 267 5100 In Canada (800)-36-FLUKE From other countries +1 (425) 446-5500 www.fluke.com/en-th

@2025 Fluke Corporation. Specifications subject to change without notice. 04/2025

Modification of this document is not permitted without written permission from Fluke Corporation.